


| <p>Product (Click on the photo to enlarge)</p> | <p>Risk</p> | <p>Measures adopted by notifying country</p> |
|--|--|---|
| <p>Category: Gas appliances and components</p> <p>Product: LPG regulator</p> <p>Brand: PEAKGAS</p> <p>Name: Lope Regulatorsaet</p> <p>Type/number of model: S200</p> <p>Batch number/Barcode: Unknown</p> <p>OECD Portal Category: 72000000 - Home Appliances</p> <p>Description: LPG regulator, 1,5 kg/h, 30 mbar, for use on gas cylinders.</p> <p>Country of origin: China</p>  | <p>Burns, Fire</p> <p>The outlet pressure is too high and the position of the spindle does not meet the requirements. This could lead to a leakage of gas if the regulator is not properly fixed on the gas cylinder.</p> <p>One accident reported.</p> <p>The product does not comply with the relevant European standard EN12864</p> | <p>Voluntary measures: Withdrawal of the product from the market</p> <p>Compulsory measures: Ban on the marketing of the product and any accompanying measures, Withdrawal of the product from the market, Recall of the product from end users</p> |